
Frank Lloyd Wright

Image:



Frank Lincoln Wright was born in 1867 in Richland Center, Wisconsin and died in 1959 in Phoenix, Arizona. Along the way he became Frank Lloyd Wright. He was the proponent of Organic Architecture, where the buildings were to be in harmony with their surroundings.

Country of origin:

United States

Life Span:

1867 - 1959

Link to Modernism Items:

- Frank Lloyd Wright

Select One:

Designer

General Tags:

- Frank Lloyd Wright